




“Fisheye” fractures in Iter.s 88, 89, 90  
AISI 8620 Composite Case+Core  
Axial Samples









See [html](#) files for details about size and location of fisheye cracks in specimens